

**2019**

**Q60011909 - ATTO H1280 PORT A can't detect  
the volume on the ARC-7212 SAS RAID  
subsystem.**

For the ATTO HBA issue, please update the ARC-5088 firmware to version 1.56-20190807 or later. You need to map PORT A & PORT B to the volume when you connect both PORT A and PORT B to the ARC-7212 SAS RAID subsystem.

Unique solution ID: #1865

Author: Simone

Last update: 2019-09-09 11:22