

2015

**Q80011403 - ARC-8050T2 can not work on
MacBook Air with OSX 10.7.5, but New Mac Pro is
ok.**

Thunderbolt 2 can only work on Mac OS X 10.8.5 or higher.

Unique solution ID: #1226

Author: Simone

Last update: 2015-08-24 08:27