

2013

Q80011311 - I couldn't get Mac OS X Mavericks boot from the raid volume on both 8050 and 5026, both thunderbolt failed. However, with the same raid volume, it boots no problem with USB 3.0 connection on 5026.

Please set the BIOS Selection option on the Advanced Configurations to EFI.

Unique solution ID: #1324

Author: Simone

Last update: 2015-08-24 08:32