

**2011 to 2012**

**Q80011411 - Areca 5026 with 4 Samsung 840 SSDs issue happens directly after creating a Raidset. Slot 3 is getting Failed Status immediately but the SSD is healthy and OK.**

ARC-5026 slot 3 and slot 4 come from a port multiplier chip. There has one bug on Samsung 840 SSD firmware that can not accept the no-zero port number (slot 3) write command on the multiplier.

Unique solution ID: #1579

Author: Simone

Last update: 2016-02-16 05:06