

**2016 to 2020**

**Q80011405 - HP Z420 computer can not detect  
ARC-5026 USB 3.0 during boot up. ARC-5026  
switches on and off shortly while the Z420 boots  
up.**

This is a compatible issue with ARC-5026 USB 3.0 and HP Z420. It has been fixed by new EPLD code on the ARC-5026 controller board.

Unique solution ID: #1560

Author: Simone

Last update: 2016-02-16 04:01