

**2016 to 2020**

**Q80031712 - OS X 10.9.5 or 10.10.5 Kernel panic occurs with any ARC-8050T3 storage. The issue is not happening using OS X 10.11.6 or macOS 10.12.5, but the client needs to stay in older macOS releases because of the version of Avid Media Composer he is using.**

Mac officially supports Thunderbolt3 since OSX 10.12.

<https://support.apple.com/en-us/HT207266>

Your Mac must be running macOS Sierra to work with the Thunderbolt 3 (USB-C) to Thunderbolt 2 Adapter. Since the new release date for OS X 10.11.6 is similar as macOS 10.12, you can connect ARC-8050T3 using Thunderbolt 3 (USB-C) to Thunderbolt 2 Adapter under OS X 10.11.6

[https://en.wikipedia.org/wiki/OS\\_X\\_El\\_Capitan](https://en.wikipedia.org/wiki/OS_X_El_Capitan)

[https://en.wikipedia.org/wiki/MacOS\\_Sierra](https://en.wikipedia.org/wiki/MacOS_Sierra)

Unique solution ID: #1722

Author: Simone

Last update: 2022-01-06 07:29