


2016 to 2020

Q80011910 - ARC-8050T3-12 is recognized as connected in ASUS X299-Deluxe II Thunderbolt software in Windows 10 Sys Tray, but drive letter never appears and device does not appear in Windows Disk Manager.


Please do below steps to check it.

- (1) Make sure this box shows connected state in thunderbolt software.



- (2) Check the Device Manager in Windows 10 to make sure this raid storage is listed with device driver loaded state. If this raid storage is not existed, please execute a hardware rescan to see any difference.

2016 to 2020



(3) It is similar to a common new disk connected. You have to partition the new disk or the volume in Windows disk manager to be able to assign a drive letter for them.

2016 to 2020

Unique solution ID: #1879

Author: Simone

Last update: 2020-08-26 08:35