## Q60011202 - The ATTO H380 has wide port issue with SAS RAID subsystem, which limited its performance since it will only connect through 1 SAS lane. The H680 performance is lower than we have expected. Does H680 have the same issue with ARC-8040?

The H680 does have the same wide port issue as ATTO 3G SAS host adapter. This is the limitation of the SAS controller chip on the H680 host adapter.

Unique solution ID: #1371

Author: Simone

Last update: 2015-08-24 06:15