

2018

Q10031705 - ARC-1882P volume set will be created using Intel S3510 SSD but it takes much longer and cause the API time out.

Firmware will send trim command to SSD during volume creation. It takes much longer time to trim the Intel S3510 SSD than previous version S3500. The trim time will cause volume time creation longer than API default time out.

Unique solution ID: #1680

Author: Simone

Last update: 2017-05-10 10:48