

**2021 to 2024**

**Q10012407 -The system fails to reboot with  
ARC-1886 RAID controller card and Supermicro  
X13DEI, regardless with configured disks or  
without. RAID function is OK from system cold  
start.**

Update the boot code to V1.68 or later version for this workaround. This workaround also applies X13DAi-T and X13DDW-A.

Unique solution ID: #2020

Author: Simone

Last update: 2024-07-21 15:06