

**2021 to 2024**

**Q10031501 - After enabling ARC-1883 “SATA Power Up In Standby “ with Adata’s SX900, a power down, and a new power up reports “failed disk”.**

This is a bug of Adata’s SX900 firmware that can’t response correctly the command to enable “SATA Power Up In Standby “. Areca has a workaround for this issue from firmware version 1.52 date: 2014-12-25 or later.

Unique solution ID: #1003

Author: Simone

Last update: 2015-04-27 06:30