

Q10021703 - ARC-1883ix cannot see any HDD when HGST JBOD 4U60 is set as SES mode.

This issue has been fixed in ARC-1883ix expander firmware version 03.01.27.51 06/06/16 or later.

Unique solution ID: #1654

Author: Simone

Last update: 2022-01-06 08:17