

Q10011708 - Is there an update for the non working "Power Up In Standby" (PUIS) command in the Firmware?

This workaround needs to contact drive vendor for the fix firmware.

Unique solution ID: #1713

Author: Simone

Last update: 2022-01-06 08:20