

Q10031311 - Under MAC PRO machine, update to firmware 1.52 all files , and then reboot it can not boot from the original bootable volume on the RAID controller.

Please set the BIOS Selection option on the Advanced Configurations to EFI.

Unique solution ID: #1294

Author: Simone

Last update: 2015-08-24 11:17