

Q10021208 - With ARC-1882ix-24, it sometimes hangs at the X8STE motherboard bios screen after reboot and sometimes hangs at Linux OS boot up screen after reboot.

It has fixed by the ARC-1882 bootcode date: 2012-04-20 or later. You can try to disable the ASPM feature in Linux loader to see if the situation is changed.

Unique solution ID: #1351

Author: Simone

Last update: 2022-01-06 08:29