

2021 to 2025

Q10022301 - I flashed the firmware to version 1.66 package then rebooted the machine, now it will only load the Areca setup utility and will not allow to boot into existed Windows. It continues to reboot into the same utility. Press F10 to reboot and it just goes back to the utility.

After firmware version 1.65, Areca RAID card ARCxxxx.BIN code creates a virtual bootable disk (UEFI OS) for RAID controller ARCxxxxUEFI.BIN code to launch the McBIOS setup utility. When M/B setup chooses to boot from the virtual disk, the McBIOS setup utility is launched through boot into UEFI OS during M/B boot. This motherboard bios may add the new boot device (the new firmware feature: UEFI OS) as the first boot device. Please enter the setup of M/B BIOS to disable or adjust UEFI OS in the boot option priorities if it is the first priority of overall boot order. Otherwise the system will always boot into UEFI OS without using the hotkey.

Unique solution ID: #2008

Author: Simone

Last update: 2024-07-21 15:07