

2018 to 2020

Q10021309 - ARC1223-8X can not detect by GA-B75-D3V (Rev1.1).

It can be fixed by the new version M/B BIOS.

Unique solution ID: #1282

Author: Simone

Last update: 2015-08-24 10:38