

2018 to 2020

Q10101311 - Black screen crashes on Mac pro with ARC-1214-8I when Mac pro reboots again.

It is a compatible issue with ROC on the controller. Update the firmware to date 2013-11-22 or later to solve the issue.

Unique solution ID: #1301

Author: Simone

Last update: 2015-08-24 11:24