

2018 to 2020

Q10011210 - Installed the ARC-1882i in the GA-Z77X-UP4 TH PClex8 and PClex4 slot, when booting, I do not see any MCBIOIS screens at all.

PCIe x8 issue has fixed by GA-Z77X-UP4 TH BIOS version F8a or later. But PCIEX4 slot can't detect PCIe X8 card due to GA-Z77X-UP4 TH PCIe x4 HW limitation.

Unique solution ID: #1353

Author: Simone

Last update: 2022-01-06 08:30