

2018 to 2020

**Q10021210 - We test install CentOS 6.3 x86_64
on Supermicro X9SCL-LN4 with ARC-1882i and
can not start the installation and hang.**

It has fixed by the ARC-1882 firmware version 1.51 or later.

Unique solution ID: #1354

Author: Simone

Last update: 2022-01-06 08:30