

2018 to 2020

Q10021111- ARC-1880LP and tried to initialize a RAID with HUS723030ALS640 disks, but the system is stopping at exactly 26,6 % of initialization.

It is bug on the foreground initialization with 3TB HDD and has fixed on the firmware V1.49 2011-09-19 or later.

Unique solution ID: #1428

Author: Simone

Last update: 2015-08-25 04:14