2018 to 2020 Q10032001 - We update OS CentOS 8.0 to 8.1, but boot is fail. Error Message is swap is not exist.

The problem is not older driver but the RHEL has removed kernel build-in driver from their kernel tree. Redhat team has removed a lot of driver source from standard kernel. You must boot system with centos8 and install the 8.1 rpm into the 8.1 kernel to be able to see this card in 8.1. If you upgrade the kernel version from default version, you will need to compile the driver module for the new kernel by yourself.

Unique solution ID: #1890 Author: Simone Last update: 2022-01-06 07:37