

2015 to 2017

Q10051406 - HP DL320 G6 doesn't recognize ARC-1882x raid adapter.

HP Server DL320G6 Slot4 (PCIe 2.0 x16/x8/x4/x1) can not work with ARC-1882x.
But Slot5 (PCIe 2.0 x4/x2/x1) LowProfilePCI can work with it.

Unique solution ID: #1136

Author: Simone

Last update: 2015-08-24 09:32