

**2015 to 2017**

**Q10031503 - What is the max CPU Temperature of an ARC-1212 or at which temperature it starts to log and throttle?**

Controller will alarm for over temperature when processor temperature is over 90 degree.

Unique solution ID: #1030

Author: Simone

Last update: 2015-08-24 08:46