

**2015 to 2017**

**Q10111106 - I'm currently testing Mac OS X Lion on my MacPro4,1 w/Areca ARC-1212. There is a severe Problem with the ArcMSR.kext shipping with both Developer Preview 3 and the latest Developer Preview 4 (11A480b): Each RAID Volume on the areca controller is detected under LUN 0 and LUN 1 and mounted twice, which of course causes severe file system corruption.**

The Lion has changed the original LUN/ID for parallel SCSI to LUN/ID for serial SCSI. Please download the driver version from our FTP or website to fix the LION compatibility.

Unique solution ID: #1409

Author: Simone

Last update: 2015-08-25 04:09