

2015 to 2017

**Q10011512 - One SSD Disk fails in the ARC-1883i
Raid Set a while in usage. After changing the
Disk, it fails after a few hours again.**

If problem occurs on various channels, you can try to disable SATA NCQ support in controller setting. Some SSDs have issue on supporting SATA NCQ while using SAS controllers.

Unique solution ID: #1537

Author: Simone

Last update: 2015-12-02 07:54