

**2015 to 2017**

**Q10021703 - ARC-1883ix cannot see any HDD  
when HGST JBOD 4U60 is set as SES mode.**

This issue has been fixed in ARC-1883ix expander firmware version 03.01.27.51  
06/06/16 or later.

Unique solution ID: #1654

Author: Simone

Last update: 2022-01-06 08:17