

2014

Q10061107 - We are using your command line interface cli32 to monitor the state of the raid array. It works fine in most cases. When I try to launch the cli32 tool it get stalled during quite a long time and give me the following error message : GuiErrMsg: Timeout.

Since the telnet port uses same interrupt as API, someone try to login the telnet port and result inquiries from CLI been ignored. Please close the telnet port through web manager console and reboot system. You can close a port by configure the port number to 0.

Unique solution ID: #1416

Author: Simone

Last update: 2015-08-25 04:11