

Q10020906 - From the Ethernet port, we got the initialization percentage 1228.8% on the ARC-1680i RAID set.

If you terminated the process when initialization or migration, and on retry the BIOS or load the driver/archhttp proxy server, firmware will be shown the unreason percentage.

The unreason percentage will be disappeared when you start the normally process.

Unique solution ID: #1529

Author: Simone

Last update: 2022-01-06 07:58