

**2021 to 2022**

## **Q30011403 - Flashing disk drives attached to an Areca SAS host adapter.**

User can use the CLI command to update HDD's firmware without necessary removing any single drive and upgrade.

Unique solution ID: #1175

Author: Simone

Last update: 2021-02-04 10:17