

Q10012407 -The system fails to reboot with ARC-1886 RAID controller card and Supermicro X13DEI, regardless with configured disks or without. RAID function is OK from system cold start.

Update the boot code to V1.68 or later version for this workaround. This workaround also applies X13DAi-T and X13DDW-A.

Unique solution ID: #2020

Author: Simone

Last update: 2024-07-21 15:06