

Q80031501 - When we install Windows Server 2012 R2 on an Areca controller, we have the option to remove the controller's volume in the OS.

In new driver codes, volumes listed as eject-able devices due to thunderbolt support.

Unique solution ID: #1063

Author: Simone

Last update: 2022-01-06 07:15