

2021 to 2024

Q60012407 - Firmware version 1.67 deletes old version firmware NTP /SNMP/ Alert By Mail configuration all entered numbers and the user needs to fill in everything again.

Based on firmware version 1.67, this firmware will modify the IP related saving space for future IPv6 support, user must refill IP settings after new firmware activated, please record current settings before activate new firmware, effected settings : SMTP, SNMP, NTP.

Unique solution ID: #2028

Author: Simone

Last update: 2024-07-21 15:22