

2012 to 2013

Q10061307 - Areca 1224 volume can be ejected without confirmation, if there is no activity on it. This requires restart which is not acceptable for US.

It has revised by the new version driver 6.20.00.28 or later version.

Unique solution ID: #1268

Author: Simone

Last update: 2015-08-24 10:34