

2012 to 2013

**Q10051203 - X8DTi-LN4F rev 1.02 with ARC-1882
on any PCIe slot, cold boot can not detect
adapter. Warm boot can detect the adapter.**

This is a bug on version 1.02 M/B. Using new version M/B can fix this bug.

Unique solution ID: #1342

Author: Simone

Last update: 2022-01-06 08:28