

2012 to 2013

Q10040906 - I have a problem to update the firmware. My Areca 1220 comes with any BIOS and I can't update BIOS with DosFlash. When I put nflash xxx.bin the program do not anything.

The DOS flash utility is an added feature which works with firmware 1.43 or later only. If your controller's firmware is older than 1.43, please update firmware and BIOS through browser manager console.

Unique solution ID: #1531

Author: Simone

Last update: 2022-01-06 07:58