

2016 to 2020

**Q50011907 - Can the 4036ML be daisy chained
from a 4036, which is connected to an 1882x
HBA?**

ARC-4036 can't support drive mode on its external port.

Unique solution ID: #1903

Author: Simone

Last update: 2021-02-04 10:40