

Q30011307 - LTFS Software can not find ARC1320-4I4X device using TDWinDrivers Ver.1.0.7 and Windows driver version 6.0.0.7.

It has fixed by ARC-1320 new version driver 6.0.0.8 or later version.

Unique solution ID: #1308

Author: Simone

Last update: 2021-02-04 10:17