

2016 to 2020

**Q10031410 - Two Bad drives: Hus724040ale640
connected to Areca 1882X, can't power on server
and time out after 300secs.**

This issue has be fixed into firmware 1.52 date: 2014-09-11 or later.

Unique solution ID: #1572

Author: Simone

Last update: 2016-02-16 04:55