

2016 to 2020

Q80011805 - Works fine on Mac, but when I try to install on Windows ARC-8050T2 does not power on.

You need to install Thunderbolt driver from M/B vendors for Windows 7/8.1/10 64-bit OS to provide the Thunderbolt functionalities. When you plug in the Thunderbolt device, follow the following link to connect ARC-8050T2 RAID storage.

<http://faq.areca.com.tw/index.php?action=artikel&cat=37&id=500&artlang=en&highlight=windows>

Unique solution ID: #1851

Author: Simone

Last update: 2022-01-06 07:25