

Q60041807 - No hardware information displayed on slave unit (controller-2) when ARC-8088-SAS is working dual controller mode.

You need to wait about 3-4 minutes later for hardware monitor synchronization ready.

Unique solution ID: #1837

Author: Simone

Last update: 2021-02-04 10:57