

Q20011704 - ARC-1882P cannot support serial mode of the fault/activity signal.

1882P does not implement the serial mode of fault/activity signal in the beginning stage. The new EPLD has added this feature on the new hardware revision B.

Unique solution ID: #1899

Author: Simone

Last update: 2020-08-26 09:15