

Q10012108 - Areca old firmware the Hardware Monitor page shows the temperatures of all installed drives. Newer raid cards and firmwares don't show the HDD temperatures until you click on a slot.

Areca newer cards no longer collect drive temperatures because SAS controllers support hundred devices, it will need much longer time to inquiry temperature from all drives, and another side effect is such action will impact performance a lot.

Unique solution ID: #1968

Author: Simone

Last update: 2021-09-15 05:51