

2010 to 2015

Q30011403 - Flashing disk drives attached to an Areca SAS host adapter.

User can use the CLI command to update HDD's firmware without necessary removing any single drive and upgrade.

Unique solution ID: #1175

Author: Simone

Last update: 2021-02-04 10:17