

2016 to 2020

Q10011512 - One SSD Disk fails in the ARC-1883i Raid Set a while in usage. After changing the Disk, it fails after a few hours again.

If problem occurs on various channels, you can try to disable SATA NCQ support in controller setting. Some SSDs have issue on supporting SATA NCQ while using SAS controllers.

Unique solution ID: #1538

Author: Simone

Last update: 2021-02-04 10:29