## Q10082102 - The ARC-1203 CPU temperature of the RAID controller is high (70°C). I would like to add a fan on the chipset. It is possible?

70°C is a normal working temperature, because the temperature is core temperature. It is higher than environment temperature. Firmware hardware monitoring feature will alarm if the CPU temperature is higher than 105°C.

If you want cool the CPU down more, you can provide a good cooling flow around the card.

Unique solution ID: #1952 Author: Simone Last update: 2021-02-25 09:41