

2010 to 2015

**Q50011410 - ARC-8028 only runs at 6Gb/s speed
on those 12 phys associated with the external
SFF-8644 connectors.**

ARC-8028 doesnot set the external port to 6Gb/s speed on any version firmware except the cable management capability enable. Please use the "CLI>cable off " comm and to disable the cable management capability function.

Cable management off= always runs at 12 Gb/s speed (for wrong Eeprom value).

Cable management on= speed depends on Eeprom on the cable that it is inquired by the expander.

Unique solution ID: #1203

Author: Simone

Last update: 2021-02-04 10:37