

**2011 to 2015**

**Q10011512 - One SSD Disk fails in the ARC-1883i  
Raid Set a while in usage. After changing the  
Disk, it fails after a few hours again.**

If problem occurs on various channels, you can try to disable SATA NCQ support in controller setting. Some SSDs have issue on supporting SATA NCQ while using SAS controllers.

Unique solution ID: #1540

Author: Simone

Last update: 2022-01-06 07:19