

**2011 to 2015**

**Q40011405 - 12Gb/s SAS HDD can not power up on the some 6Gb/s SAS backplanes.**

Power Disable (T10 Industry Standard) for remote management of the end device. Allows power cycling / power saving to be controlled by the host via interface pin 3.

The power segment, precharge pin P3 is connected to the two V33 pins P1 and P2 on the SAS 1.1/2/2.1 drive backplane receptacle connector. But on SAS 3.0, P3 is used to redefine as a POWER DISABLE signal: Asserted voltage (power disabled) 2.1V to 3.6V. This will cause the 12Gb/s SAS HDD on the power disable stage. P3 is not connected behind a SAS drive plug connector if the POWER DISABLE signal is unsupported.

Unique solution ID: #1191

Author: Simone

Last update: 2015-08-24 08:35