

2009 to 2011

Q10031103 - We has tested the ARC-1880 with battery by pulling power during write to the RAID. In this case, the Areca BIOS fails to load on the following power up, so the NVS content cannot flush to restore the RAID data.

It is a bug of firmware version before 1.49 date:2011-02-18.

Unique solution ID: #1384

Author: Simone

Last update: 2015-08-25 04:04